

## Sparex Service Info




TD43813/4

Part Nr. S.43813/ S.43814

Perkins – A3.152 AD3.152

MASSEY FERGUSON – 35 35X 135 Rope Seal

Info: Sump Modification required when replacing Perkins A3.152 and AD3 152 short motors fitted with rope type rear main oil seals fitted between 1959 and 1975.



Issued 07.2020 / TD43813/4 / Technical content subject to change  
OE Manufacturers names and numbers are used for reference purposes only  
© Sparex Limited