



Certificate of Conformity

Certificate Number: DL-20210713009C

Applicant: Guangzhou Besyo Auto Parts Co., LTD
1208, the 12th floor, Xiangyun Building, NO.1400 Baiyun Avenue, Baiyun district, Guangzhou.China 510440

Manufacturer: Guangzhou Besyo Auto Parts Co., LTD
1208, the 12th floor, Xiangyun Building, NO.1400 Baiyun Avenue, Baiyun district, Guangzhou.China 510440

Product: Wireless Monitor

Trade Mark: 

M/N: BY-08127W
BY-08050W, BY-08512W, BY-08514W, BY-08517W, BY-08207W,
BY-08217W, BY-08237W, BY-08107W, BY-08307W, BY-08317W,
BY-08117W, BY-08118W, BY-08137W, BY-08147W, BY-08109W,
BY-08219W, BY-08319W, BY-08101W, BY-08104W, BY-08105W

Essential requirement		Applied Standards	Report Number
Art.3.1(a)	Health	BS EN 62479:2010, BS EN 50663:2017	DL-20210713009-1E
Art.3.1(b)	EMC	ETSI EN 301 489-1 V2.2.3 (2019-11) ETSI EN 301 489-17 V3.2.4 (2020-09)	DL-20210713009-2E
Art.3.2	Radio	ETSI EN 300 440 V2.2.1 (2018-07)	DL-20210713009-3E
Art.3.1(a)	Safety	BS EN 62368-1:2014+A11:2017	DL-20210713009-4S

The EUT described above has been tested by us with the listed standards and found in compliance with the council Radio Equipment Regulations 2017. It is possible to use UKCA marking to demonstrate the compliance with this Directive. It is only valid in connection with the test report number as listed.

UK CA



This certificate of conformity is based on a single evaluation of the submitted sample(s) of the above mentioned product. It does not imply an assessment of the whole product and relevant. Without the written approval, It is not permitted to use the test lab's logo.

Shenzhen DL Testing Technology Co., Ltd.
101-201, Building C, Shuanghuan, No.8, Baoqing Road, Baolong Industrial Zone, Baolong Street, Longgang District, Shenzhen, Guangdong, China

Web: www.dl-cert.com E-mail: Service@dl-cert.com Tel: 400-688-3552

